



## API/EI Research Report 545-A

Verification of lightning protection  
requirements for above ground  
hydrocarbon storage tanks

First edition, October 2009



API/EI Research Report 545-A

Verification of lightning protection requirements for above ground  
hydrocarbon storage tanks

First edition

October 2009

Published jointly by

**API**  
and

**ENERGY INSTITUTE LONDON**

The Energy Institute is a professional membership body incorporated by Royal Charter 2003  
Registered charity number 1097899

This is a preview. [Click here to purchase the full publication.](#)

Copyright © 2009 by API, and  
The Energy Institute, London:  
The Energy Institute is a professional membership body incorporated by Royal Charter 2003.  
Registered charity number 1097899, England  
All rights reserved.

No part of this book may be reproduced by any means, or transmitted or translated into a machine language without the written permission of the publisher.

ISBN 978 0 85293 376 3

Published by the Energy Institute

The information contained in this publication is provided as guidance only and while every reasonable care has been taken to ensure the accuracy of its contents, the Energy Institute cannot accept any responsibility for any action taken, or not taken, on the basis of this information. The Energy Institute shall not be liable to any person for any loss or damage which may arise from the use of any of the information contained in any of its publications.

Further copies can be obtained from:  
Portland Customer Services, Commerce Way, Whitehall Industrial Estate, Colchester, CO2 8HP, UK.  
t: +44 (0) 1206 796 351 e: **sales@portland-services.com**

or

Global Engineering Documents at (800) 854-7179 or (303) 397-7956  
w: **www.global.ihs.com**

Electronic access to EI publications is available via our website, **www.energyinstpubs.org.uk**.  
Documents can be purchased online as downloadable pdfs or on an annual subscription for single users and companies.  
For more information, contact the EI Publications Team e: **pubs@energyinst.org**

This is a preview. Click here to purchase the full publication.

## CONTENTS OVERVIEW

	Page
Legal notices and disclaimers. ....	iv
Foreword .....	v
 <b>PHASE 1</b>	
Acknowledgements .....	i
Executive summary. ....	ii
<b>Cul/LT-0234</b>	
Review of lightning phenomena and the interaction with above ground storage tanks ..	1
<b>Cul/LT-0235</b>	
Review of tank base earthing and test current recommendations. ....	43
<b>EI-EN2-04</b>	
Lightning tests to tank shell/shunt samples. ....	55
<b>EI-Vis1-01</b>	
Visit to oil refinery A .....	73
<b>EI-Vis2-02</b>	
Visit to oil refinery B. ....	83
<b>EI-TN1-03</b>	
Review of burn-through and hot-spot effects on metallic tank skins from lightning strikes ..	93
 <b>PHASE 2</b>	
Acknowledgments .....	i
Executive Summary .....	ii
<b>Cul/LT-0373</b> Lightning simulation testing to determine the required characteristics for roof bonding cables on external floating roof above ground storage tanks. ....	1
<b>Cul/LT-0401</b> Investigative tests on the lightning protection of submerged shunts with parallel roof bonding cables .....	31

## LEGAL NOTICES AND DISCLAIMERS

The information contained in this publication is provided as guidance only, and although every effort has been made by API and EI to assure the accuracy and reliability of its contents, API and EI MAKE NO GUARANTEE THAT THE INFORMATION HEREIN IS COMPLETE OR ERROR-FREE. ANY PERSON OR ENTITY MAKING ANY USE OF THE INFORMATION HEREIN DOES SO AT HIS/HER/ITS OWN RISK. TO THE MAXIMUM EXTENT PERMITTED BY APPLICABLE LAW, THE INFORMATION HEREIN IS PROVIDED WITHOUT, AND API AND EI HEREBY EXPRESSLY DISCLAIM, ANY REPRESENTATION OR WARRANTY OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, INCLUDING, WITHOUT LIMITATION, WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE AND NON-INFRINGEMENT. IN NO EVENT SHALL API OR EI BE LIABLE TO ANY PERSON, OR ENTITY USING OR RECEIVING THE INFORMATION HEREIN FOR ANY CONSEQUENTIAL, INCIDENTAL, PUNITIVE, INDIRECT OR SPECIAL DAMAGES (INCLUDING, WITHOUT LIMITATION, LOST PROFITS), REGARDLESS OF THE BASIS OF SUCH LIABILITY, AND REGARDLESS OF WHETHER OR NOT API OR EI HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR IF SUCH DAMAGES COULD HAVE BEEN FORESEEN.

The contents of this publication are not intended or designed to define or create legal rights or obligations, or set a legal standard of care.

API or EI is not undertaking to meet the duties of manufacturers, purchasers, users and/or employers to warn and equip their employees and others concerning safety risks and precautions, nor is API or EI undertaking any of the duties of manufacturers, purchasers, users and/or employers under local and regional laws and regulations. This information should not be used without first securing competent advice with respect to its suitability for any general or specific application, and all entities have an independent obligation to ascertain that their actions and practices are appropriate and suitable for each particular situation and to consult all applicable federal, state and local laws.

API AND EI HEREBY EXPRESSLY DISCLAIM ANY LIABILITY OR RESPONSIBILITY FOR LOSS OR DAMAGE RESULTING FROM THE VIOLATION OF ANY LOCAL OR REGIONAL LAWS OR REGULATIONS WITH WHICH THIS PUBLICATION MAY CONFLICT.

Nothing contained in any API or EI publication is to be construed as granting any right, by implication or otherwise, for the manufacture, sale, or use of any method, apparatus, or product covered by letters patent. Neither should anything contained in the publication be construed as insuring anyone against liability for infringement of letters patent.

No reference made in this publication to any specific product or service constitutes or implies an endorsement, recommendation, or warranty thereof by API or EI.

API, EI, AND THEIR AFFILIATES, REPRESENTATIVES, CONSULTANTS, AND CONTRACTORS AND THEIR RESPECTIVE PARENTS, SUBSIDIARIES, AFFILIATES, CONSULTANTS, OFFICERS, DIRECTORS, EMPLOYEES, REPRESENTATIVES, AND MEMBERS SHALL HAVE NO LIABILITY WHATSOEVER FOR, AND SHALL BE HELD HARMLESS AGAINST, ANY LIABILITY FOR ANY INJURIES, LOSSES OR DAMAGES OF ANY KIND, INCLUDING DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, OR PUNITIVE DAMAGES, TO PERSONS, INCLUDING PERSONAL INJURY OR DEATH, OR PROPERTY RESULTING IN WHOLE OR IN PART, DIRECTLY OR INDIRECTLY, FROM ACCEPTANCE, USE OR COMPLIANCE WITH THIS PUBLICATION.

## FOREWORD

This publication has been produced at the request of the API RP 545 Task Force and the EI Electrical Committee.

It collates a number of research reports produced by Culham Electromagnetics and Lightning Limited (Culham) who were commissioned to investigate the lightning phenomena and the adequacy of lightning protection measures on above ground hydrocarbon storage tanks.

Currently international, British and United States standards contain requirements relating to lightning protection; however, these have not been verified through practical, scientific testing. As a result of the work commissioned by the API and EI, a new Recommended Practice (RP) is being developed which will incorporate the results of this investigation.

Suggested revisions are invited and should be submitted to the director of standards, API, 1220 L Street, N.W., Washington, D.C. 20005 or The Technical Department, Energy Institute, 61 New Cavendish Street, London, W1G 7AR.





API/EI RESEARCH REPORT

VERIFICATION OF LIGHTNING PROTECTION REQUIREMENTS  
FOR ABOVE GROUND HYDROCARBON STORAGE TANKS

PHASE 1



## EXECUTIVE SUMMARY

### CUL/LT-0234

#### REVIEW OF LIGHTNING PHENOMENA AND THE INTERACTION WITH ABOVE GROUND STORAGE TANKS

This document describes the phenomena of lightning, and how it is expected to interact with various types of tank designs, in particular with respect to the problems of hydrocarbon fires. It draws on the experience of refinery and tank farm visits by the author, including those reported in EI-Vis1-01 *Visit to oil refinery A* and EI-Vis2-02 *Visit to oil refinery B*, and other sources. The likely strike points on all types of tanks are described, and the current routes over tanks are shown for the fast and slow lightning components. The shunt/rim seal region for an open top FRT is shown to be the most susceptible to ignitions. Aluminium roof geodesic tanks appear to be the most likely type to suffer hot spots and burn through. The electrical properties of steel as a material for tanks is described along with descriptions of thermal and voltage sparking. Protection strategies for open FRTs, for roofed over tanks, and LPG tanks are described. Comments are made on the problems associated with petroleum product within the pontoons or on the surface of a floating roof. An analysis of the operation of the shunt/shell bonding cable suggests that it would play a vital part in suppressing sparking from the continuing current component of lightning, although it would play only a minor role in suppressing sparking from the fast component. The principal USA/UK lightning protection and oil industry documents are reviewed for their content on lightning protection of tanks.

### CUL/LT-0235

#### REVIEW OF TANK BASE EARTHING AND TEST CURRENT RECOMMENDATIONS

The earthing of a storage tank may have important considerations for safety, and protection of instrumentation on the tank, but in practice the tank is likely to be intrinsically well earthed simply by its construction. Even so earthing rods should be (and are) generally used as recommended by international standards. Quality of earthing has little or no significance in storage tank fire protection. The document also discusses the likely currents which shunts may have to carry (up to 11 kA).

### EI-EN2-04

#### LIGHTNING TESTS TO TANK SHELL/SHUNT SAMPLES

Tests at Culham replicated shunt/shell interfaces and subjected them to conducted lightning-type currents. Even clean steel shunt/shell interfaces sparked. Fast current components produce relatively small sparks, whereas long duration currents produce copious spark showers that are believed to be more hazardous. (In practice good protection against the latter currents can be achieved using a roof bonding cable.) Different shunt materials could also present less of a hazard. Currents in immersed shunts tended to cause an eruption of fluid, due to the arc pressure.